

Test Records

Tests performed by: PAT Testing One Two One Two

Treforest

pontypridd , cf37

msnurse@hotmail.co.uk

Martin Ego - DJ

Asset ID	397	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Martin Ego - DJ

Asset ID	396	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	395	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Twin - DJ

Asset ID	394	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
l eakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Tv Pwr - DJ

Asset ID	393	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available







Tv - D	J
--------	---

Asset ID	392	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

8 Meter Extension - DJ

Asset ID	391	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	390	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Karaoke Machine - DJ

Asset ID	389	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Rcf Top - DJ

Asset ID	388	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

· · · · · · · · · · · · · · · · · · ·					
	Test name	Limit	Measured value	Status	
	Visual			Pass	

No photo available







Rcf Top - DJ

Asset ID	387	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Long Black 6 Gang - DJ

Asset ID	386	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest Results - Class I				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Long Black 6 Gang - DJ

Asset ID	385	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec - Powercon - DJ

Asset ID	384	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Powercon - DJ

Asset ID	383	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				 No photo available
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







			-	

Asset ID	382	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

rest Results - Class I				No photo available
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Long lec - DJ

Asset ID	381	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Long lec - DJ

Asset ID	380	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

hoto available

Overall status: Pass

lec Cable - DJ

Asset ID	379	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

available

Overall status: Pass

lec Extension - DJ

Asset ID	378	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

lest Results - 0	Ne shete available			
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







_		_	-		_	_
				-		

Asset ID	377	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	376	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	375	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest Results - Cit	No photo ovoilable			
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	374	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

i cot i courto ciu	No photo ovoilable			
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	373	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

	No photo available			
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







Asset ID	372	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	371	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Freedom Par - DJ

Asset ID	370	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

	•		
Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Freedom Par - DJ

Asset ID	369	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

	vicual city			
Test name	Limit	Measured value	Status	
Micual			Dacc	

No photo available

Overall status: Pass

Freedom Par - DJ

Asset ID	368	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

· · · · · · · · · · · · · · · · · · ·					
Test name	Limit	Measured value	Status		
Visual			Pass		

No photo available







Freedom Par - DJ

Asset ID	367	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	366	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	365	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	364	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	363	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

	No photo available			
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







	_		_
Pwr /		ntar	
	_\ • r • r		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

Asset ID	362	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Freedom Par - DJ

Asset ID	361	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Freedom Par - DJ

Asset ID	360	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Freedom Par - DJ

Asset ID	359	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

rest itesails tisaai ciiig					
	Test name	Limit	Measured value	Status	
	Micual			Dacc	

No photo available

Overall status: Pass

Freedom Par - DJ

Asset ID	358	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

• • • • • • • • • • • • • • • • • • • •					
Test name	Limit	Measured value	Status		
Visual			Dass		

No photo available







Selfie Wizard Power - DJ

Asset ID	357	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Selfie Wizard Power - DJ

Asset ID	356	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Moving Head - DJ

Asset ID	355	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	354	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	· ·
Visual			Pass	
Earth bond	0.1 Ω	<0.1Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Moving Head - DJ

Asset ID	353	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/Δ

Test Results - Visual only

i de l'il de la comp						
Test name	Limit	Measured value	Status			
Visual			Pass			

No photo available







lec Cable - DJ

Asset ID	352	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Moving Head - DJ

Asset ID	351	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	350	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Moving Head - DJ

Asset ID	349	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

. cst .tcsa.t	o visuai oiliy		
Test name	Limit	Measured value	Status
Vicual			Dacc

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	348	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	110 prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







				г	_			-				
-	I =1	m	e	IV	ы	T cal	1	m	e	-	ID.	N I

Asset ID	347	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	346	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Flame Machine - DJ

Asset ID	345	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest results - class i				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	344	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest itesuits eluss i				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	343	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

			No photo available	
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







Martin Ego - DJ

Asset ID	342	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Martin Ego - DJ

Asset ID	341	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Moving Head - DJ

Asset ID	340	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	339	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	ио р
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Moving Head - DJ

Asset ID	338	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status	
Visual			Pass	

No photo available







lec Cable - DJ

Asset ID	337	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Rcf Top - DJ

Asset ID	336	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Rcf Top - DJ

Asset ID	335	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Disco Ball Motor - DJ

Asset ID	334	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest itesuits Glass i				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Disco Ball Motor - DJ

Asset ID	333	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







UV Cannon - DJ

Asset ID	332	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

UV Cannon - DJ

Asset ID	331	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Powercon - DJ

Asset ID	330	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 ΜΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Powercon - DJ

Asset ID	329	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest itesuits Glass i				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

UV Cannon - DJ

Asset ID	328	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

rest Results - Visual Offiy					Nonh
	Test name	Limit	Measured value	Status	No ph
	Visual			Pass	

No photo available







Rush - DJ

Asset ID	327	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Powercon - DJ

Asset ID	326	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

o available

Overall status: Pass

White 6 Gang - DJ

Asset ID	325	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest Results - C	Nia alaasa ayadalala			
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	324	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No phot
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	323	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

	No photo available			
Test name	Limit	Measured value	Status	110 prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







	Ca	_		

Asset ID	322	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

White 6 Gang - DJ

Asset ID	321	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	320	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	319	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Tri 64 - DJ

Asset ID	318	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

rest Results - Visual Only				
Test name	Limit	Measured value	Status	
Visual			Pass	

No photo available







Tri 64 - DJ

Asset ID	317	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

UV Cannon - DJ

Asset ID	316	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Rcf Top - DJ

Asset ID	315	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Rcf Top - DJ

Asset ID	314	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	313	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	2025/07/15

Test Results - Class I

rest results - class i				No photo available
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







No photo available

White 6 Gang - DJ

Asset ID	312	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Single Extension - DJ

Asset ID	311	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest Results - Class I				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	310	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 ΜΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	309	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	308	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	110 prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







No photo available

No photo available

No photo available

lec Cable - DJ

Asset ID	307	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

lec Cable - DJ

Asset ID	306	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Cdj Pwr - DJ

Asset ID	305	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Pioneer Cdj - DJ

Asset ID	304	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status	
Visual			Pass	

No photo available

No photo available

Overall status: Pass

Cdj Pwr - DJ

Asset ID	303	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass







Pioneer Cdj - DJ

Asset ID	302	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	301	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Pioneer Mixer - DJ

Asset ID	300	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	299	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No pi
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Pioneer Mixer - DJ

Asset ID	298	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status		
Visual			Dass		

No photo available







Pioneer Cdj - DJ

Asset ID	297	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	296	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Pioneer Cdj - DJ

Asset ID	295	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	294	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest itesuits Glass i				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Radio Mic Receiver - DJ

Asset ID	293	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status		
Visual			Pass		

No photo available







_		•		•			_	_
10)	24		M		D۱A	/r -	רו	1

Asset ID	292	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Feedback Destroyer - DJ

Asset ID	291	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	290	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Chauvet Lf5 - DJ

Asset ID	289	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	288	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	NO PHOLO available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







Chauvet Gobo - DJ

Asset ID	287	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

No photo available

Overall status: Pass

Overall status: Pass

lec Cable - DJ

Asset ID	286	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Chauvet Gobo - DJ

Asset ID	285	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	284	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest results class i				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

lec Cable - DJ

Asset ID	283	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	140 prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







lec Cable - DJ

Asset ID	282	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Overdii Status. Pas

lec Cable - DJ

Asset ID	281	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test Results - Class I

rest Results - class i				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Helix Gobo - DJ

Asset ID	280	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

No photo available

Overall status: Pass

Helix Gobo - DJ

Asset ID	279	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	278	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	NO PHOTO available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







	_			_	_
	E 🕶) -		•
 104	EX.	 151			~ .

Asset ID	277	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test name	Limit	Measured value	Status	IN
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	276	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	275	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				No
Test name	Limit	Measured value	Status	140
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	274	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	273	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







	_			_	_
	E 🕶) -		•
 104	EX.	 151			~ .

Asset ID	272	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	271	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	270	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	269	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	ING
Visual			Pass	
Earth bond	0.1 Ω	<0.1Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Tri 64 - DJ

Asset ID	267	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

rest Results - Visual Only					
Test name	Limit	Measured value	Status		
Visual			Pass		

No photo available







Tri 64 - DJ

Asset ID	266	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Tri 64 - DJ

Asset ID	265	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Tri 64 - DJ

Asset ID	264	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Tri 64 - DJ

Asset ID	263	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	262	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

	No photo available			
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







Asset ID	261	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test name	Limit	Measured value	Status	IN
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	260	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	259	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

photo available

Overall status: Pass

lec Extension - DJ

Asset ID	258	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Extension - DJ

Asset ID	257	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

lest Results -	No photo ovoiloble			
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







Tri 64 - DJ

Asset ID	256	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Tri 64 - DJ

Asset ID	255	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Tri 64 - DJ

Asset ID	254	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Large Laser - DJ

Asset ID	253	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	252	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







Projector - DJ

Asset ID	251	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	250	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Mini Laser - DJ

Asset ID	249	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

rest Results - C	No photo ovoilable			
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Air Dmx Bridge - DJ

Asset ID	248	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Air Dmx Bridge - DJ

Asset ID	247	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status		
Visual			Dass		

No photo available

No photo available

Overall status: Pass



Matthew Nurse



Air Dmx Bridge - DJ

Asset ID	246	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Air Dmx Bridge - DJ

Asset ID	245	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Mini Strobe - DJ

Asset ID	244	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Mini Strobe - DJ

Asset ID	243	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Ac Adapter - DJ

Asset ID	242	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available







Star		

Asset ID	241	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Star Cloth Controller - DJ

Asset ID	240	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

Test name	Limit	Measured value	Status
Visual			Pass

No photo available

Overall status: Pass

Rcf Sub - DJ

Asset ID	239	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	N
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Rcf Sub - DJ

Asset ID	238	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Radio Mic Receiver - DJ

Asset ID	237	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	N/A

Test Results - Visual only

restriction risual crity				
	Test name	Limit	Measured value	Status
	Visual			Pass

No photo available







_	-	•		_		_	_
10)	ചപ		M	DVA	/r -	П	

Asset ID	236	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Disco Ball Motor - DJ

Asset ID	235	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Strip Light - DJ

Asset ID	234	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Strip Light - DJ

Asset ID	233	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Strip Light - DJ

Asset ID	232	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	_	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







lec Cable - DJ

Asset ID	231	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	230	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Long lec - DJ

Asset ID	229	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	
	Visual Earth bond Insulation			

Overall status: Pass

Long lec - DJ

Asset ID	228	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

reserves class i				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Long lec - DJ

Asset ID	227	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	110 prioto avaliable
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







No photo available

No photo available

Long lec - DJ

Asset ID	226	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

Overall status: Pass

Long lec - DJ

Asset ID	225	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
I eakage	5 mA	<5 mA	Pass

Overall status: Pass

Long Black 6 Gang - DJ

Asset ID	224	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

				No photo available
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Long Black 6 Gang - DJ

Asset ID	223	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

Overall status: Pass

Rcd - DJ

Asset ID	222	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - RCD

	No photo available			
Test name	Limit	Measured value	Status	No prioto avaliable
Visual			Pass	
Rated	30 mA	30 mA	Info	
X1 Δt	200 ms	<200 ms	Pass	
X5 ∆t	40 ms	<40 ms	Pass	







_		_	-	_	_	

Asset ID	221	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test name	Limit	Measured value	Status	IN:
Visual			Pass	
Earth bond	0.1 Ω	<0.1Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	220	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	+	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

lec Cable - DJ

Asset ID	219	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

hoto available

Overall status: Pass

lec Cable - DJ

Asset ID	218	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	No photo
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

o available

Overall status: Pass

8 Meter Extension - DJ

Asset ID	217	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

lest Results - Class I				No photo ovoilable
Test name	Limit	Measured value	Status	No photo available
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	







10 Meter Extension -	L)	J.	

Asset ID	216	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

8 Meter Extension - DJ

Asset ID	215	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status
Visual			Pass
Earth bond	0.1 Ω	<0.1 Ω	Pass
Insulation	1 ΜΩ	>1 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

10 Meter Extension - DJ

Asset ID	214	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class I

Test name	Limit	Measured value	Status	
Visual			Pass	
Earth bond	0.1 Ω	<0.1 Ω	Pass	
Insulation	1 ΜΩ	>1 MΩ	Pass	
Leakage	5 mA	<5 mA	Pass	

No photo available

Overall status: Pass

Adapter - DJ

Asset ID	213	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

Ac Adapter - DJ

Asset ID	212	Test date	2024/07/15
Client	SGDJ ltd	Next visual test	2025/07/15
Site	-	Next full test	2025/07/15

Test Results - Class II

Test name	Limit	Measured value	Status
Visual			Pass
Insulation	2 ΜΩ	>2 MΩ	Pass
Leakage	5 mA	<5 mA	Pass

No photo available

Overall status: Pass

END OF RESULTS



